Wisconsin Department of Natural Resources

Environmental Cleanup & Brownfields Redevelopment

BRRTS on the Web

Click the Location Name below to view the Location Details page for this Activity. Other Activities, if present, may be viewed from that page.

BOTW Home > Basic Search > Search Results > 03-64-127899 Activity Details

03-64-127899 TOWER STANDARD SERVICE

and a 1 ST base 0 Safe 1 shows



Cleanup has been approved at this location but some contamination remains. Due to this remaining residual contamination, one or more continuing obligations are applicable to this location (e.g., an asphalt cap or other barrier covering the contamination). For information specific to the continuing obligations at this location, read the Closure Letter within the GIS Registry Packet in the Documents section below. For general information on managing continuing obligations and residual contamination click here. You must contact DNR before constructing a well. Remaining contamination must be properly handled if disturbed.

| Location Name | County | WDNR Region | | | | | | | |
|--|---------------------|-------------------------------------|-------------------------------|---|-----------------------|---------------------|--|--|--|
| TOWER STAND | VILAS | NORTHERN | | | | | | | |
| Address | | Municipality | | | | | | | |
| 14267 STH 70 W | 1 | LAC DU FLAMBEAU | | | | | | | |
| Public Land Sur | vey Sy | stem | Latitude | Google Maps | RR Sites Map | | | | |
| SE 1/4 of the SW | ′ 1/4 of | Sec 30, T40N, R05E | 45.9137567 | CLICK TO VIEW | CLICK TO VIEW | | | | |
| Additional Locat | tion De | scription | Longitude | Facility ID | Size (Acres) | | | | |
| NONE | | | -89.9132072 | 764158560 | .5 | | | | |
| Jurisdiction | | PECFA No. | EPA Cerclis ID | Start Date | End Date | Last Action | | | |
| DNR RR | Š | 5 <u>4538-9517-67</u> | | 1997-05-07 | | 2015-03-17 | | | |
| Characteristics | | | | | | | | | |
| PECFA Tracked? | EPA NPL Site? | Eligible for PECFA Funds? | Above Ground Storage Tank? | Drycleaner? | Co- Contamination? | On GIS Registry? | | | |
| Yes | No | Yes | No | No | Yes | Yes | | | |
| Actions Place Cursor Over Action Code to View Description | | | | | | | | | |
| Date | Code | Name | | Comment | | | | | |
| 1997-05-07 | 1 | Notification | | | | | | | |
| 1997-05-23 | 2 | RP Letter Sent | | | | El Company | | | |
| 1997-06-03 | 35 | Site Investigation Work (w/out Fee) | orkplan Received | | | | | | |
| 1998-08-28 | 99 | Miscellaneous | | SEE CASETRACK 97-NOEE-007 | | | | | |
| 1998-10-01 | 99 | Miscellaneous | | PRIVATE WELL AT SERVICE STATION CONTAM. W/BENZENE | | | | | |
| 1999-05-24 | 37 | SI Report Received | (w/out Fee) | | | | | | |
| 1999-07-28 | 38 | Site Investigation Re | eport Approved | SENT LETTER | | | | | |
| 2000-06-21 | 99 | Miscellaneous | | CONSULTANT HIRED | | | | | |
| 2000-09-15 | 43 | Status Report Recei | ved | | | | | | |
| * | | • | | | | | | | |

| 2000-09-15 | 99 | Miscellaneous | | ADEQUATE RPT | | | | | |
|---|--------|--|--|---|----------------|--|--|--|--|
| 2000-09-19 | 99 | Miscellaneous | | WPDES PERMIT APPROVAL | | | | | |
| 2002-02-22 | 99 | Miscellaneous | | REDUCED SAMPLING REQUEST GRANTED | | | | | |
| 2003-05-06 | 92 | O&M Report Received (w/o | out Fee) | O&M REPORT & REMEDIATION DOCUMENTATION REPORT | | | | | |
| 2003-05-09 | 93 | O&M Report Approved | | | | | | | |
| 2004-05-21 | 43 | Status Report Received | THE STATE OF THE S | minima i i i i i i i a a a a i i i i i i i | | | | | |
| 2005-01-04 | 43 | Status Report Received | 100 | REPORT #3 | | | | | |
| 2005-10-03 | 43 | Status Report Received | | | | | | | |
| 2006-02-23 | 710 | Date Soil Registry Fee Paid | d | | | | | | |
| 2006-02-23 | 50 | GIS Registry Site | | | | | | | |
| Linked to Co | de 50: | | | to Download or Open | | | | | |
| 2006-02-23 | 79 | Closure Review Request Received | | \$1200 TOWER SERVICE CHECK WEISTER | # 7274. | | | | |
| 2006-02-23 | 700 | Date Groundwater Registry Fee Received | | | | | | | |
| 2006-04-06 | 80 | Closure Not Approved | | INCREASING TREND FOR BENZENE IN MW-9 | | | | | |
| 2006-06-06 | 179 | Closure Review Request Received (no fee required) | | RESUBMITTAL. NO FEE. WEISTER. | | | | | |
| 2006-09-15 | 236 | Continuing Obligation - Residual GW Contamination | | | | | | | |
| 2006-09-15 | 12 | Activity Formerly Closed | | | | | | | |
| 2006-09-15 | 232 | Continuing Obligation - Residual Soil Contamination | | | | | | | |
| 2006-10-21 | 100 | GIS Registry QAQC Completed | | | | | | | |
| 2014-02-06 | 99 | Miscellaneous | | SEE 09-64-561652 NOTIFICATION NAR | N, EVAULATE AS | | | | |
| 2015-03-17 | 13 | Activity Reopened | | | | | | | |
| | | | Impacts | | | | | | |
| Туре | | Comm | nent | | | | | | |
| Co-contamination | | - | | | | | | | |
| Contaminated Privates Contaminated | - | | | | | | | | |
| Groundwater Cont | | LION - | | | | | | | |
| Off-Site Contamin | | | | | | | | | |
| Son Contamination | I | | Substances | | | | | | |
| Substance | | Ty | | Amount | Units | | | | |
| Gasoline - Unlead | ed and | Leaded | Petroleum | | | | | | |
| Who | | | | | | | | | |
| | | Click name of Project Ma | | Contact to compose email | | | | | |
| Role | | | N | ame/Address | | | | | |
| Consultant REI ENGINEERING INC 4080 N 20TH AVE WAUSAU, WI 54401 | | | | | | | | | |
| RP Contact/Agent | | WILLIAM KOZAK 8760 W | SQUAW LAF | (E RD LAC DU FLAMBEAU, WI 5 | 4538 | | | | |
| Project Manager GREER LUNDQUIST 107 SUTLIFF AVE RHINELANDER, WI 54501 | | | | | | | | | |
| Quick Response Codes 😡 Scan the QR Code to transfer to your wireless device | | | | | | | | | |
| | | | | | | | | | |
| 8 | | ı | | ı | | | | | |

This Page URL Google Maps GIS Registry PDF

BRRTS data comes from various sources, both internal and external to DNR. There may be omissions and errors in the data and delays in updating new information. Please see the <u>disclaimers page</u> for more information.



The Official Internet site for the Wisconsin Department of Natural Resources 101 S. Webster Street . PO Box 7921 . Madison, Wisconsin 53707-7921 . 608.266.2621

Release 2.3 | 02/13/2015 | Release Notes